

## Release Note for Vigor2762 Series

Firmware Version:	3.8.9.2
Release Type:	Normal
Applied Models:	Vigor2762, Vigor2762n, Vigor2762ac, Vigor2762Vac

Vigor2762 series, the high speed router, are perfectly complied with VDSL2 environment including Vigor2762n and Vigor2762ac for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2762 series, you can simultaneously engage these bandwidth-intensive applications, such as high-definition video streaming, online gaming, and Internet telephony / access.

### File and Modem Code

**Note:** For DSL models, there will be two folders: STD and MDM. The files in MDM folder named folder include different modem codes. If you're using a VDSL line, MDM firmware may brings out better performance.

Available modem codes for Annex A/Annex B are displayed as follows:

#### For Annex A Model,

- "Vigor2762\_v3.8.9.2\_STD.zip" is used for modem code 776d07\_772801 & 774307\_771801
- "Vigor2762\_v3.8.9.2\_MDM1.zip" is used for modem code 779517\_773F01 & 776d07\_772801.
- "Vigor2762\_v3.8.9.2\_MDM2.zip" is used for modem code 77B506\_775401 & 776d07\_772801.

#### For Annex B Model,

- "Vigor2762\_v3.8.9.2\_STD.zip" is used for modem code 773306\_771502 & 773307\_771C02.
- "Vigor2762\_v3.8.9.2\_MDM1.zip" is used for modem code 773306\_771502 & 773307\_771C02.
- "Vigor2762\_v3.8.9.2\_MDM2.zip" is used for modem code 773306\_771502 & 773307\_771C02.

### New Features

- Support 4G LTE dongle, QP QLD310 with PPP mode.

## Improvement

- Improved: Enhanced the security on the web server.
- Corrected: The information in Dashboard, Bind IP to MAC, and View ARP Cache Table was not displayed periodically.
- Corrected: VDSL connection was unstable.
- Corrected: Firewall did not work on routed LAN.
- Corrected: DSL bandwidth auto detection for QoS didn't work.
- Corrected: LAN configuration change disabled routing mode set previously.
- Corrected: When attempting to apply multiple static routes on the Vigor router through VigorACS, only the first route profile could be created.
- Corrected: Static routes applied by VigorACS (with \*.xml) not always held after rebooting CPE.
- Corrected: Unable to access the web user interface by using a particular cloud server.

## Known Issue

- None.