NO:AP1101-2 V.1

Release Note for VigorAP 807

Firmware Version:	5.1.2
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	VigorAP 807

VigorAP 807 is an 11be wireless mesh access point. It provides the flexibility and advanced features for professional users to take full management of the wireless network, including the mesh technology, which aims for providing an easy way to expand the wireless network in minutes.

New Features

- Support the "Allow management from WLAN" option under System Maintenance > Management > Service Control.

Improvement

- Improved: Strengthened Linux kernel security to mitigate CVE-2024-36971, CVE-2024-1086, CVE-2021-22600, CVE-2022-2586, CVE-2022-0492, CVE-2022-0185, CVE-2024-50302, and CVE-2025-38352.
- Improved: Updated the 802.11r compatibility note to indicate that some wireless clients may experience connectivity or roaming issues when 802.11r is enabled.
- Improved: Active management sessions are now invalidated when the associated account is deleted, disabled, has its password or TOTP settings changed, or is assigned a different role.
- Corrected: An issue where the AP could not be added to AP Management on a DrayOS4 router.
- Corrected: An issue where a CA-signed certificate could not be imported after its CSR was generated on the AP.
- Corrected: An issue where enabling Two-Factor Authentication caused a Web UI login timeout even when the correct verification code was entered.
- Improved: Hardened the TR-069 configuration path by writing the ACS server URL and credentials directly to the configuration file, removing a privileged command-injection vector.
- Corrected: Issues related to IPv6 AH (Authentication Header) handling (CVE-2026-80844, "DirtyAH6") and PPPoE packet handling (CVE-2026-68121, "PPPoEject").

Known Issue

- DrayTek MFUU can only work through Ethernet port P2 and P3.

Notes

- None.