## **Release Note for Vigor120 Series**

Firmware Version: 3.2.2
Date: March 2, 2009
Applied Models:
Vigor120

- File and Modem Code
  - (1)For Annex A Model,
    - ➤ "v120\_a\_v322" is used for modem code 321311. (Standard)
    - > "v120\_a1\_v322" is used for modem code 310801.
    - > "v120\_a2\_v322" is used for modem code 310811.
    - > "v120\_a3\_v322" is used for modem code 3211201
    - > "v120\_a4\_v322" is used for modem code 332201.

#### **New Features**

None

## **Improvement**

- Corrected: PPP connection for WAN3/4/5 may drop for a while.
- Modify the words for "ATM Statistics" on the online status web page.
   (ATM Statistics TX Cells RX Cells TX CRC errs RX CRC errs)
- Corrected: "Multi-PVC channel" item cannot be shown on PPPoE/PPPoA web page
- Add "DS Interleave Depth"/"US Interleave Depth" information for the telnet command adsl status.
- Corrected: Some problem happened in MPoA bridge mode.

### **Known Issue**

None

# **Notes**

## Modifications

• None