

Release Note for Vigor120 Series

Firmware Version: 3.2.4.2

Built Date: March 11, 2010

Applied Models:

Vigor120

- File and Modem Code
 - (1)For Annex A Model,
 - "v120_a_v3242" is used for modem code 321311. (Standard)
 - "v120_a1_v3242" is used for modem code 310801.
 - "v120_a2_v3242" is used for modem code 310811.
 - "v120_a3_v3242" is used for modem code 3211201
 - "v120_a4_v3242" is used for modem code 332201.
 - "v120_a5_v3242" is used for modem code 343601.
 - "v120_a6_v3242" is used for modem code 343701 (recommended for Italy).
 - "v120_a7_v3242" is used for modem code 3431301.
 - "v120_a8_v3242" is used for modem code 344001.
 - "v120_a9_v3242" is used for modem code 344101.

New Features

- Support VigorACS SI.
- Support STUN for TR-069.

Improvement

- Corrected: On WAN side, connections with two PPPoA or above cannot work normally.
- Corrected: Authentication of connection request in TR-069 must be answered with "MD5" but not "md5".
- Improved: A problem occurred in protocol verification on **NAT >> Port Redirection** page after clicking **OK**.
- Improved: got problem with IE8 on **System Maintenance >> Administrator Password Setup** page.
- Improved: got interoperability problem with Safari and Firefox on Mac OS 10.6.

Known Issue

- None

Notes

Modifications

- None