Release Note for Vigor2700 Series

Firmware Version: 2.8.4.1 Release Date: July 1, 2014 Applied Models:

Vigor2700, Vigor2700G, Vigor2700V(2S/2S1L), Vigor2700VG(2S/2S1L), Vigor2700Gi (Annex B), Vigor2700VGi (Annex B)

• File and Modem Code

(1)For Annex A Model,

- > "v2k7v_a_2841" is used for modem code 121201. (Standard)
- > "v2k7v_a1_2841" is used for modem code 113111.
- ➤ "v2k7v_a2_2841" is used for modem code 131701. (Recommended for UK-SEG)
- "v2k7v_a3_2841" is used for modem code 1401201. (Recommended for USA or for G.lite environment)
- > "v2k7v_a4_2841" is used for modem code 1411301.
- > "v2k7v_a5_2841" is used for modem code 142201.

(2)For Annex B Model,

- \sim "v2k7v_b_2841" is used for modem code 131812. (Standard)
- > "v2k7v_b1_2841" is used for modem code 113112.
- \sim "v2k7v_b2_2841" is used for modem code 1211202.
- ➤ "v2k7v_b3_2841" is used for modem code 1311302. (Recommended for Germany)
- \triangleright "v2k7v_b4_2841" is used for modem code 1401302.
- \blacktriangleright "v2k7v_b5_2841" is used for modem code 1411402.
- "v2k7v_b6_2841" is used for modem code 142112. (Support T1.413 Annex B, recommended for Spain)
- \sim "v2k7v_b7_2841" is used for modem code 142402.

New Features

• None

Improvement

• Corrected: CVE-2014-0224 CCS injection vulnerability.

Known Issue

• None

Notes

Modifications

• None