Release Note for Vigor3900 Series

Firmware Version:	1.5.1.5
Release Type:	Critical - Upgrade immediately
Applied Models:	Vigor3900

Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.8.x and later.

New Features

• None.

Improvement

• Improved: Improve Web GUI Security.

Known Issue

The new firmware version 1.5.1.4 removes the support of the character "%" as the admin password to enhance the WebGUI security. If the character "%" is used as the admin password, please change the password before upgrading to the new firmware version. If the character "%" is used as the admin password and you've upgraded to the new firmware version without changing the password, please use the following CLI commands via Telnet/SSH to change the admin password.
enable
configure system
admin passwd

1