

## Release Note for Vigor2760 Series (Delight)

Firmware Version:	3.8.9.4
Release Type:	Normal
Applied Models:	Vigor2760, Vigor2760n, Vigor2760Vn

DrayTek launches Vigor2760 series – high speed router, perfectly complied with VDSL2/ADSL2/ADSL2+ environment including Vigor2760, Vigor2760n and Vigor2760Vn for speed-wanted customers. For more details of the product information, please visit our website on <http://www.draytek.com>.

### File and Modem Code

**Note:** For DSL models, there will be two folders: STD and VECTOR. The files in VECTOR folder implement a new DSL driver, which supports G.Vectoring on VDSL. If you're using a VDSL line, VECTOR firmware may brings out better performance; however, please consult your ISP to check if G.Vectoring is required. We also provide several versions of Vector firmware to avoid the interoperability issue. You could just try the other one if the one you use cannot synchronize or get the speed that you expected.

Available modem codes for Annex A/Annex B are displayed as follows:

#### For Annex A Model,

- "Vigor2760\_v3.8.9.4\_STD.zip" is used for modem code 548006\_544401 & 560816\_552011.
- "Vigor2760\_v3.8.9.4\_VECTOR1.zip" is used for modem code 567517\_562301 & 566f07\_562701.
- "Vigor2760\_v3.8.9.4\_VECTOR2.zip" is used for modem code 574307\_571801 & 573807\_571701.
- "Vigor2760\_v3.8.9.4\_VECTOR3.zip" is used for modem code 576d17\_572801 & 574307\_571801.
- "Vigor2760\_v3.8.9.4\_VECTOR4.zip" is used for modem code 579F17\_573F01 & 573807\_571701.

#### For Annex B Model,

- "Vigor2760\_v3.8.9.4\_STD.zip" is used for modem code 548006\_544512 & 551716\_553312.
- "Vigor2760\_v3.8.9.4\_VECTOR1.zip" is used for modem code 565607\_567002 & 565606\_567002.
- "Vigor2760\_v3.8.9.4\_VECTOR2.zip" is used for modem code 573307\_571c02 &

565607\_567002.

- "Vigor2760\_v3.8.9.4\_VECTOR3.zip" is used for modem code 573307\_571c02 & 565607\_567002.
- "Vigor2760\_v3.8.9.4\_VECTOR4.zip" is used for modem code 573307\_571c02 & 565607\_567002.

## New Features

- None.

## Improvement

- Improved: Add Dynu DDNS provider setting on Applications>>Dynamic DNS Setup>>Dynamic DNS Account Setup.
- Improved: Add an option to specify which LAN/Source IP will be used for TR-069 management (System Maintenance>>TR-069 Setting).
- Improved: A warning message will appear when LAN1 subnet is not used for LAN port or SSID.
- Improved: A warning message appears before all TLS/SSL protocols are disabled.
- Improved: Add an option to select which WPA PSK to be used when applying default configuration file via CLI.
- Improved: Support Vietnam SMS provider.
- Corrected: Vigor router ignored Don't Fragment flag in IP header.
- Corrected: Data quota set on User Management>>User Profile would be reset to zero after re-login.
- Corrected: Invalid note appeared in WAN>> General Setup. USB WAN was fixed to backup mode (failover).
- Corrected: Config restoration failed in VPN LAN to LAN, Bind IP to MAC and Wireless Access Control List via HTTPS.
- Corrected: Disabling IPv6 corrupted the GUI of the Dashboard.

## Known Issue

- None.