Release Note for Vigor2120 Series

Firmware Version: 3.7.5.2
Release Date: September 24, 2014
Applied Models:
Vigor2120, Vigor2120n-plus

Vigor2120 series is a broadband router, which integrates IP layer QoS, NAT session and bandwidth management to help users control works well with large bandwidth.

New Features

- None.

Improvement

- Corrected: Fixed the problem of memory usage after PPPoE disconnection.
- Corrected: The option of "IPv6" should be checked in default as Block routing packet from WAN in the General Setup tab on Firewall>>General Setup.
- Corrected: Vigor router would reboot when accessing Web UI via HTTPS with WAN IP from LAN.
- Corrected: Wireless clients access into Internet via 2.4GHz and 5GHz. Later, 2.4GHz wireless connection would be disconnected due to unknown reason.
- Corrected: LAN may fall into storm loop if connecting to Win7/Win8 PC with McAfee installed.
- Corrected: Could not send .def firmware file to Vigor2120 successfully.

Known Issue

- URL Redirect on the page of LAN>>Web Portal Setup does not accept HTTPS domain names.
- VigorACS SI can not get some variables of Wireless LAN (5 GHz)>>General Setup of this router.

Notes

Modifications

- ● None