Release Note for Vigor2920 Series

Firmware Version: 3.3.2.2
Built Date: February, 10, 2009
Applied Models:
Vigor2920/Vigor2920n

Vigor2920 series, a firewall broadband router with dual-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet. The gigabit 2^{nd} WAN and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- Display username or password error message in login page.
- Support the function of Factory Reset for TR-069.

Improvement

- Corrected: Correct some problems in WUI.
- Corrected: "GetRPCMethodsResponse" returns wrong count of methods for TR-069.
- Corrected: Return HTTP status code "409 Conflict" while performing the update for TR-069.
- Corrected: Get "VoiceProfileNumberOfEntries" by Profile Name or Domain/Realm for TR-069.
- Corrected: Apply "My WAN IP field" to IPSec NAT mode for **CheckPoint** router.
- Corrected: LAN may not work after powering off/on.

Known Issue

- None

Notes

Modifications

- None