Release Note for VigorAP 800

Firmware Version: 1.1.5
Release Date: December 22, 2014
Applied Models: VigorAP 800

"With this high cost-efficiency VigorAP 800, computers and wireless devices which are compatible with 802.11n can connect to the existing Ethernet network via this VigorAP800. 300Mbps wireless transmission rates is ideal for bandwidth-heavy tasks. Easy install procedures allow any computer users to setup a network environment in very short time - within minutes, even inexperienced users."

New Features

- None.

Improvement

- Corrected: After enabling Bandwidth Management for Wireless LAN 5G, only the upload limit setting is available. The download limit did not work.
- Corrected: Wireless LAN 5G Security settings configured in Quick Start Wizard did not work.
- Corrected: When Station-Infrastructure was chosen for Wireless LAN(2.4G), WPA Algorithms for **Wireless LAN(5G)>>Security** could not configured and saved successfully. Hence, the value for **Key Renewal Interval** was shown as "undefined".
- Corrected: Fixed the burn-in problem.
- Corrected: The configuration files for **Enable DHCP Client** in **LAN>>General Setup** between the old firmware version and the new firmware version are not compatible.
- Corrected: The fields design for **Upload Limit** and **Download Limit** in **Wireless LAN>>Bandwidth Management** were reverse.
- Corrected: Non-existed channel setting (configured in **Central AP Management>>WLAN Profile** of Vigor router) would be shown on **System Maintenance>>System Status** on VigorAP800.
- Corrected: CVE 2014-3566 POODLE vulnerability.

Known Issue

- None

Notes

Modifications

- None