Release Note for VigorAP 1000C

Firmware Version:	1.4.0
Release Type:	Normal
Applied Models:	VigorAP 1000C

VigorAP 1000C is a ceiling-mount Wi-Fi for business networks. As a tri-band AP, it provides an extra 5GHz Wireless band which increases the supported number of wireless devices. In Mesh mode or Range Extender mode, this extra band can also be dedicated as the Uplink band to the Internet. VigorAP 1000C is suitable to construct a small Wireless network.

New Features

- Support new authentication mechanism for MyVigor server.

Improvement

- Improved: Let Mesh Root enter Register state automatically when an Isolated Wired Mesh Node in Group List is detected.
- Improved: Close TCP port 9608 when it is not used (e.g., not in Mesh Root mode and Root AP disabled) to improve security.
- Corrected: An issue of wireless roaming.
- Corrected: An issue that mail alert did not work.
- Corrected: An issue of image modification on quick start wizard.
- Corrected: An issue that Wireless VLAN ID did not work when LACP was enabled.
- Corrected: An issue that OK button on web Wireless LAN>>Access Control had no effect.

Known Issue

- System performance will drop when Bonding is enabled.

Note

- The throughput figures are maximum, based on DrayTek internal testing with optimal conditions. The actual performance may vary depending on the different network conditions and applications activated.