Release Note for VigorAP 1000C

Firmware Version:	1.4.3
Release Type:	Normal
Applied Models:	VigorAP 1000C

VigorAP 1000C is a ceiling-mount Wi-Fi for business networks. As a tri-band AP, it provides an extra 5GHz Wireless band which increases the supported number of wireless devices. In Mesh mode or Range Extender mode, this extra band can also be dedicated as the Uplink band to the Internet. VigorAP 1000C is suitable to construct a small Wireless network.

New Features

- Add the master AP group ID and group key.
- Add the default DHCP client ID for identifying VigorAP.

Improvement

- Improved: Support AP management using SSH.
- Improved: Improve the OpenSSL security (CVE-2022-0778).
- Improved: Support APP (DrayTek Wireless) config backup/restore function.
- Improved: Support "AutoSelect" for the 2.4GHz channel as the default setting.
- Improved: Add a note to remind the user that the system will reboot after finishing the firmware upgrade.
- Improved: Add a note and a pop-up alert to notify the user not to enable Management VLAN when using the Mesh function.
- Corrected: An issue of WiFi stability.
- Corrected: A display issue of LAN-B information on APM.
- Corrected: An issue of clients communicating with each other with the same radio but different SSIDs.

Known Issue

- System performance will drop when Bonding is enabled.

Note

- The throughput figures are maximum, based on DrayTek internal testing with optimal conditions. The actual performance may vary depending on the different network conditions and applications activated.