NO:AP1101-2 V.1

Release Note for VigorAP 805

Firmware Version:	5.1.2
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	VigorAP 805

VigorAP 805 is 11ax wireless mesh access point. It provides the flexibility and advanced features for professional users to take full management of the wireless network, including the mesh technology, which aims for providing an easy way to expand the wireless network in minutes.

New Features

- None.

Improvement

- Improved: Strengthened Linux kernel security to mitigate CVE-2024-36971, CVE-2025-38352, CVE-2026-68121, and CVE-2026-80844.
- Improved: Enhanced the device management/application security to mitigate CVE-2026-89014, CVE-2026-89015, and CVE-2026-89016.
- Corrected: An issue where Interface VLAN did not work after the AP rebooted.
- Corrected: An issue where enabling Two-Factor Authentication led to a login timeout.

Known Issue

- None.

RD NO: 115_11_06