

Release Note for Vigor120 Series

Firmware Version: 3.2.4.1
Built Date: October 30, 2009
Applied Models:
Vigor120

- File and Modem Code
 - (1)For Annex A Model,
 - "v120_a_v3241" is used for modem code 321311. (Standard)
 - "v120_a1_v3241" is used for modem code 310801.
 - "v120_a2_v3241" is used for modem code 310811.
 - "v120_a3_v3241" is used for modem code 3211201
 - "v120_a4_v3241" is used for modem code 332201.
 - "v120_a5_v3241" is used for modem code 343601.
 - "v120_a6_v3241" is used for modem code 343701 (recommended for Italy).
 - "v120_a7_v3241" is used for modem code 3431301.

New Features

- Add a new VPI/VCI=2/40 into Auto Detection table for Norway.

Improvement

- Corrected: "GLite" item on WUI for annex A is lost.
- Corrected: PPPoE may be enabled when we set Internet Access on MPoA mode.
- Corrected: VPN pass-through cannot work.

Known Issue

- None

Notes

Modifications

- None