NO: AP1101-2 V.1

Release Note for Vigor2130 Series

Firmware Version: 1.5.4.1 Release Date: July 15, 2014 Applied Models:

Vigor2130, Vigor2130n, Vigor2130Vn

The Vigor2130 series are the routers with high speed in data transmission through WAN port and LAN ports. With hardware NAT acceleration, the rate of Vigor2130 series can be greater than 800 Mbps almost.

New Features

None.

Improvement

- Corrected: CVE-2014-0224 CCS injection vulnerability.
- Corrected: VoIP SIP Register Status error in TR-069.
- Corrected: Traffic control rule does not work in 3G backup mode.
- Corrected: IGMP Snooping drops all IGMP packets received from a VLAN-Tagged WAN.
- Corrected: VPN LED is still on when L2TP/IPsec connection is down.
- Corrected: An error occurs that DHCP release unexpectedly for the command of *udhcpc* is not end yet.
- Improved: Add switch port for SNMP traffic analysis.

Known Issue

None

Notes

• User Mode with empty password is forbidden for security issue