

Release Note for Vigor2700 Series

Firmware Version: 2.8.5.2

Release Date: October 27, 2014

Applied Models:

**Vigor2700, Vigor2700G, Vigor2700V(2S/2S1L), Vigor2700VG(2S/2S1L),
Vigor2700Gi (Annex B), Vigor2700VGi (Annex B)**

- File and Modem Code

(1)For Annex A Model,

- "v2k7v_a_2852" is used for modem code 121201. (Standard)
- "v2k7v_a1_2852" is used for modem code 113111.
- "v2k7v_a2_2852" is used for modem code 131701. (Recommended for UK-SEG)
- "v2k7v_a3_2852" is used for modem code 1401201. (Recommended for USA or for G.lite environment)
- "v2k7v_a4_2852" is used for modem code 1411301.
- "v2k7v_a5_2852" is used for modem code 142201.

(2)For Annex B Model,

- "v2k7v_b_2852" is used for modem code 131812. (Standard)
- "v2k7v_b1_2852" is used for modem code 113112.
- "v2k7v_b2_2852" is used for modem code 1211202.
- "v2k7v_b3_2852" is used for modem code 1311302. (Recommended for Germany)
- "v2k7v_b4_2852" is used for modem code 1401302.
- "v2k7v_b5_2852" is used for modem code 1411402.
- "v2k7v_b6_2852" is used for modem code 142112. (Support T1.413 Annex B, recommended for Spain)
- "v2k7v_b7_2852" is used for modem code 142402.

New Features

- Support Annex J for ADSL over ISDN line.

Improvement

- Corrected: When pressing OK to save the SIP Account settings, the SIP Expiry time will be changed into Manual and the time is set as "0". It will cause SIP incoming call cannot be received.

Known Issue

- None

Notes

- Please backup your configuration of web settings first before upgrading the firmware v2.8.5 or later.
- Please select modulation to "Multimode" or "ADSL2 Annex M" or "ADSL2+ Annex M" to enable Annex J. Modem code should be 1311302 or later for Annex B.