

Release Note for Vigor2762 Series

Firmware Version:	3.9.6
Release Type:	Normal
Applied Models:	Vigor2762, Vigor2762n, Vigor2762ac, Vigor2762Vac

Vigor2762 series, the high speed router, are perfectly complied with VDSL2 environment including Vigor2762n and Vigor2762ac for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2762 series, you can simultaneously engage these bandwidth-intensive applications, such as high-definition video streaming, online gaming, and Internet telephony / access.

New Features

- Support a new encryption mechanism for license obtaining, network connecting, and registering to the MyVigor server.
- Support LTE dongle (161c:f010).

Improvement

- Corrected: An issue of 2.4GHz function LED display error on Dashboard.

Known Issue

- None.

File and Modem Code

Note: For DSL models, there will be two folders: STD and MDM. The files in MDM folder named folder include different modem codes. If you're using a VDSL line, MDM firmware may brings out better performance.

Available modem codes for Annex A/Annex B are displayed as follows:

- "Vigor2762_v3.9.6_STD.zip" provides Annex A modem code 776d07_772801 & 774307_771801, and Annex B modem code 773306_771502 & 773307_771C02.
- "Vigor2762_v3.9.6_MDM1.zip" provides Annex A modem code 779517_773F01 & 77B507_775401, and Annex B modem code 779B06_774F02 & 779B07_774C12.
- "Vigor2762_v3.9.6_MDM2.zip" provides Annex A modem code 77B506_775401 &

778C06_773F01, and Annex B modem code 779906_774402 & 779B06_774C02.

- "Vigor2762_v3.9.6_MDM3.zip" provides Annex A modem code 77C817_775A11 & 77C717_775A11, and Annex B modem code 77C717_775A12 & 779B07_774C12.