Release Note for Vigor2135 Series

Firmware Version:	4.3.2.1
Release Type:	Normal
Applied Models:	Vigor2135 / Vigor2135Vac / Vigor2135FVac
	Vigor2135ac / Vigor2135Fac / Vigor2135FV

Vigor2135 features advanced bandwidth control mechanism such as IP-layer, QoS, NAT Session Limitation, Bandwidth Borrowed, etc., to allow easy, flexible, reliable access control and bandwidth management.

New Features

• None.

Improvement

- Corrected: An issue of system stability and router reboot.
- Corrected: An issue of self-signed certificate regeneration automatically of Vigor router before expiration.
- Corrected: An issue of Hardware Acceleration failed to accelerate the WAN to LAN sessions in the routing mode.

Note

• None.

Known Issue

• Do not downgrade the firmware of Vigor router to 4.2.1, if subnet 3 and 4 are enabled.