

## Release Note for Vigor2862 Series

Firmware Version:	3.8.8.2
Release Type:	Critical
Applied Models:	Vigor2862 / Vigor2862n / Vigor2862ac / Vigor2862Vac / Vigor2862L / Vigor2862Ln / Vigor2862Lac

Vigor2862 series is a VDSL2 router with multi-subnet for secure and efficient workgroup management. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. Besides, “n” and “ac” series have built-in Wireless LAN for wireless connection.

**This is a critical update - You should upgrade such Vigor router immediately with firmware containing these improvements.**

### New Features

- None.

### Improvement

- This firmware includes improvements to harden the web interface against attacks. We have become aware of specific attacks against router, including DrayTek models where hackers have altered specific settings relating to your DNS servers and DHCP settings. You should urgently check those settings on your router. If they appear to have been tampered with, correct them and change your admin password and for any other config anomalies. Restore a config backup if you have one (from prior to the attack). We continue to investigate this issue but the first priority was to issue updated firmware.

### File and Modem Code

For DSL models, there will be three folders: STD, VT1 and VT2. The files in VT named folder include different modem codes. If you're using a VDSL line, VT named firmware may bring out better performance. Available modem codes for Annex A/Annex B are displayed as follows:

#### For Annex A Model,

- "Vigor2862\_3.8.8.2\_STD\_en.7z" is used for modem code 776d07\_772801 & 774307\_771801
- "Vigor2862\_3.8.8.2\_VT1\_en.7z" is used for modem code 779517\_773F01 &

776d07\_772801 (recommended for Australia)

- "Vigor2862\_3.8.8.2\_VT2\_en.7z" is used for modem code 77B506\_775401 & 776d07\_772801

**For Annex B Model,**

- "Vigor2862\_3.8.8.2\_STD\_en.7z" is used for modem code 773306\_771502 & 773307\_771C02
- "Vigor2862\_3.8.8.2\_VT1\_en.7z" is used for modem code 773306\_771502 & 773307\_771C02
- "Vigor2862\_3.8.8.2\_VT2\_en.7z" is used for modem code 773306\_771502 & 773307\_771C02

## Known Issue

- None.