

Release Note for VigorSwitch P2280x

Firmware Version:	2.9.11
Loader Version:	3.5.1
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	VigorSwitch P2280x

VigorSwitch P2280x, 24 Gigabit Ports + 4 SFP Ports PoE L2 Managed Switch, is a standard switch that meets both IEEE 802.3u/ab Fast Ethernet and Gigabit Ethernet specifications.

New Features

- None.

Improvement

- Improved: Improve the OpenSSL security.
- Improved: Improved the TR-069 configuration page.
- Improved: Improved the password strength checking method.
- Corrected: An issue with unabling to login to the VigorSwitch WUI due to the web cache.
- Corrected: An issue where the user could not log in to the VigorSwitch WUI after the Eylan logo was added to the login page.

Known Issue

- Unable to downgrade the switch using the firmware version below 2.7.x if the loader version used currently is 3.5.1.
- The fans may not work at full speed on the new P2280x when using firmware version 2.8.2. Please do not downgrade the firmware to version 2.8.2, especially when the switch's original version is 2.8.4.

Note

- STP (Spanning Tree Protocol) is enabled by default starting from firmware version 2.9.8, which may result in a slightly longer link-up time for ports.