### Release Note for Vigor2700 Series

Firmware Version: 2.8.5
Release Date: August 5, 2014
Applied Models:

Vigor2700, Vigor2700G, Vigor2700V(2S/2S1L), Vigor2700VG(2S/2S1L), Vigor2700Gi (Annex B), Vigor2700VGi (Annex B)

- File and Modem Code
  - (1)For Annex A Model,
    - ➤ "v2k7v\_a\_285" is used for modem code 121201. (Standard)
    - > "v2k7v\_a1\_285" is used for modem code 113111.
    - ➤ "v2k7v\_a2\_285" is used for modem code 131701. (Recommended for UK-SEG)
    - "v2k7v\_a3\_285" is used for modem code 1401201. (Recommended for USA or for G.lite environment)
    - > "v2k7v a4 285" is used for modem code 1411301.
    - > "v2k7v a5 285" is used for modem code 142201.

#### (2)For Annex B Model,

- ➤ "v2k7v\_b\_285" is used for modem code 131812. (Standard)
- > "v2k7v b1 285" is used for modem code 113112.
- ➤ "v2k7v b2 285" is used for modem code 1211202.
- ➤ "v2k7v\_b3\_285" is used for modem code 1311302. (Recommended for Germany)
- ➤ "v2k7v\_b4\_285" is used for modem code 1401302.
- ➤ "v2k7v b5 285" is used for modem code 1411402.
- ➤ "v2k7v\_b6\_285" is used for modem code 142112. (Support T1.413 Annex B, recommended for Spain)
- ➤ "v2k7v\_b7\_285" is used for modem code 142402.

#### **New Features**

Support configuration encoding/decoding.
 Please backup your configuration first before upgrading the firmware, v2.8.5.

### **Improvement**

None.

# **Known Issue**

• None

# **Notes**

## **Modifications**

• None