Release Note for Vigor2765 Series

Firmware Version:	4.3.2.1
Release Type:	Normal
Applied Models:	Vigor2765, Vigor2765ac, Vigor2765Vac

Vigor2765 is a VDSL2 35b router which is suitable for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2765, you can simultaneously engage these bandwidth-intensive applications, such as high-definition multimedia content, online music, movie streaming and file sharing.

New Features

• None.

Improvement

- Corrected: An issue of system stability and router reboot.
- Corrected: An issue of MDM3 firmware cannot switch to ADSL modem code.
- Corrected: An issue of self-signed certificate regeneration automatically of Vigor router before expiration.
- Corrected: An issue of Hardware Acceleration failed to accelerate the WAN to LAN sessions in the routing mode.

Known Issue

• None.

Notes

- Vigor2765ac only supports WDS in wireless 5G.
- This version allows up to 4 LAN subnets to be configured. To avoid continuous system reboot, only the RST file can be used for firmware downgrading.

File and Modem Code

- "Vigor2765_v4.3.2.1_STD.zip" provides Annex A modem code 8B0F07_8B0701, 8B2607_8B0B01 and Annex B 8B2607_8B0B02, 8B2817_8B0812.
- "Vigor2765_v4.3.2.1_MDM1.zip" provides Annex A modem code 8B1117_8B0701, 8B0F07_8B0701 and Annex B 8B2817_8B0812, 8B2607_8B0B02.
- "Vigor2765_v4.3.2.1_MDM2.zip" provides Annex A modem code 8D1917_8D0C11, 8D1507_8D0901 and Annex B 8D1917_8D0C12, 8B2817_8B0812.
- "Vigor2765_v4.3.2.1_MDM3.zip" provides Annex A modem code 77C717_8D0C11, 8D1507_8D0901 and Annex B 77C717_8D0C12, 8B2607_8B0B02.