Release Note for Vigor2960

Firmware Version:	1.3.3.1
Release Type:	Normal
Applied Models:	Vigor2960 Series

Vigor2960, a firewall broadband router with dual-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet FTTx. The dual-WAN and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.9 or later.

New Features

None.

Improvement

- Improved: Improvement related to firmware security.
- Corrected: Issues related to unstable VPN disconnection.
- Corrected: Remote dial-in users failed to make VPN connection under certain conditions.

Known Issue

• None.

RD NO: 107_03_28