Release Note for VigorAP 800

Firmware Version: 1.0.3.1 Built Date: February 21, 2012 Applied Models: VigorAP 800

With this high cost-efficiency VigorAP 800, computers and wireless devices which are compatible with 802.11n can connect to existing wired Ethernet network via this VigorAP 800, at the speed of 300Mbps. Easy install procedures allows any computer users to setup a network environment in very short time - within minutes, even inexperienced users.

New Features

• Enable IGMP snooping for Wireless in default.

Improvement

- Improved: Default WLAN security is TKIP/AES.
- Improved: Solve the problem of WPS vulnerability.
- Fixed: XBOX 360 can not connect to AP800 with WPA2.
- Fixed: VigorACS cannot read AP800's parameters.
- Fixed: "Parameters-Wireless-Station List" makes the AP800 losing connection to VigorACS SI server.
- Fixed: Modify default configuration to fix WMM problem.

Related Information

- Get the document, please visit
 http://www.draytek.com/user/PdInfoDetail.php?Id=122
- Get the new firmware, please visit
 http://www.draytek.com/user/SupportDownloads.php
- Get the customer service support, please visit http://www.draytek.com/user/ContactHeadquarters.php
- Get the regulatory compliance information http://www.draytek.com/user/AboutRegulatory.php

Get information for global partners
 http://www.draytek.com/user/Globalpartners.php

Known Issue

None

Notes

Modifications

None