

# Release Note for VigorAP 800

**Firmware Version: 1.1.0**

**Release Date: May 14, 2013**

**Applied Models: VigorAP 800**

---

With this high cost-efficiency VigorAP 800, computers and wireless devices which are compatible with 802.11n can connect to existing wired Ethernet network via this VigorAP 800, at the speed of 300Mbps. Easy install procedures allows any computer users to setup a network environment in very short time - within minutes, even inexperienced users.

## New Features

- Support a new telnet command for rebooting the router.

## Improvement

- Fixed: Fixed the error of NTP server time update.
- Fixed: The result for changing the rate for "11b Only" wireless mode from "11Mbps" to "Auto" cannot be saved correctly.
- Fixed: The default value (1812) for RADIUS Server Setup was not filled on the page of Quick Start Wizard>>2.4G Security.
- Fixed: When WDS settings were added from AP discovery web page, the subnet would not be changed.

## Related Information

- Get the document, please visit  
<http://www.draytek.com/user/PdInfoDetail.php?Id=122>
- Get the new firmware, please visit  
<http://www.draytek.com/user/SupportDownloads.php>
- Get the customer service support, please visit  
<http://www.draytek.com/user/ContactHeadquarters.php>
- Get the regulatory compliance information  
<http://www.draytek.com/user/AboutRegulatory.php>
- Get information for global partners

## **Known Issue**

- None

## **Notes**

### ***Modifications***

- None