# **Release Note for VigorAP 910C**

#### Firmware Version: 1.1.7.2 Release Date: September 19, 2016 Applied Models: VigorAP 910C

VigorAP 910C is a ceiling mount Access Point with PoE for offering power supply and support 300Mbps @2.4GHz, and 866Mbps @5GHz (11ac).

### **New Features**

• None.

# Improvement

- Corrected: After rebooting VigorAP, settings made by VigorACS could not be written to VigorAP successfully for the first time.
- Corrected: PC (Win10) couldn't re-connect to VigorAP wireless with EAP-TLS RADIUS EAP Type in WPA2/802.1x security mode.
- Corrected: Universal repeater (5G) didn't work when pass phrase contained ';' character (semicolon).
- Corrected: Fixed the problem of slow connection for accessing router's web user interface via HTTPS.
- Corrected: Fixed errors related to TR-069 settings.

# **Known Issue**

• None

#### Notes

#### Modifications

• None

- 2 -